

# WATER WELL REPORT

STATE OF WASHINGTON

31/06-10A

Application No

Permit No

(1) OWNER: Name Jon Stoneman Address 2506 W. Lake Sammamish Rd. S.E. Bell  
(2) LOCATION OF WELL: County Island - NE 1/4, NE 1/4 Sec. 10 T. 31 N. R. 2 W.M.  
Bearing and distance from section or subdivision corner W. Camano Dr.

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐  
Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: (Owner's number of well (if more than one))  
New well ☒ Method: Dug ☐ Bored ☐  
Deepened ☐ Cable ☐ Driven ☐  
Reconditioned ☐ Rotary ☒ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.  
Drilled 333 ft. Depth of completed well 280 ft.

(6) CONSTRUCTION DETAILS:  
Casing installed: 6 " Diam. from 0 ft. to 323 ft.  
Threaded ☐ " Diam. from     ft. to     ft.  
Welded ☒ " Diam. from     ft. to     ft.

Perforations: Yes ☒ No ☐  
Type of perforator used Kite  
SIZE of perforations 1/4" in. by 1 1/4" in.  
perforations from 245 ft. to 255 ft.  
perforations from     ft. to     ft.  
perforations from     ft. to     ft.

Screens: Yes ☐ No ☒  
Manufacturer's Name      
Type     Model No      
Diam.     Slot size     from     ft. to     ft.  
Diam.     Slot size     from     ft. to     ft.

Gravel packed: Yes ☐ No ☒ Size of gravel:      
Gravel placed from     ft. to     ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.  
Material used in seal Bentonite  
Did any strata contain unusable water? Yes ☐ No ☒  
Type of water?     Depth of strata      
Method of sealing strata off    

(7) PUMP: Manufacturer's Name Jacuzzi  
Type: Submersible H.P. 1 1/2

(8) WATER LEVELS: Land-surface elevation above mean sea level     ft.  
Static level 222 1/2 ft. below top of well Date 6-2-87  
Artesian pressure     lbs. per square inch Date      
Artesian water is controlled by     (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level      
Was a pump test made? Yes ☒ No ☐ If yes, by whom? D. L. W. And.  
Yield: 15 gal./min. with 7 ft. drawdown after 4 hrs.  
" " " " " "  
" " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level
1 Min.	227' 8"				
2 Min.	225' 10"				
3 Min.	222' 7"				

Date of test 6-1-87  
Ball test 15 gal./min. with 5 ft. drawdown after     hrs.  
Artesian flow     g.p.m. Date      
Temperature of water     Was a chemical analysis made? Yes ☐ No ☒

## (10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

Brown Cl MATERIAL	FROM	TO
Brown Clay & Gravel	0	46
Blue Clay & Gravel	46	53
Brown Clay & Gravel	53	230
Blue Clay & Gravel	230	248
Brown Clay & Gravel & Water	248	253
Sandy Brown Clay	253	270
Blue Clay	270	333

Bentonite Plug at bottom of hole  
Perforated 245-255'  
filled in above plug to 280'

Work started 5-20-87, 19    Completed 5-27-87, 19   

## WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME DAHLMAN PUMP & WELL DRILLING, INC.  
(Person, firm, or corporation) (Type or print)

Address Box 422, Burlington, WA. 98233

[Signed] H. Ken Fowler  
(Well Driller)

License No. 1192 0623 Date 6-2-87, 19